

Ben Snow March/16  
V Max II lead A/E drawing

- 1) Red Glad hand P/N 10010451E
- 2) Air gauge 460 gauge 100 psi
- 3) Rocker box P/N RA011R-C001
- 4) Blue Glad hand P/N 10010452S
- 5) Mac valve p/n 100225B604CC209
- 6) 3 way ball valve's p/n 100BU2101C
- 7) Solenoid's p/n 100A68230
- 8) Speed up valve p/n 100110580
- 9) 1 way check valve p/n 1010200
- 10) pressure protection valve p/n 226PPV90606SCC
- 11) 1 way ball valve P/N 100BV2103D
- 12) 3030 air pot's p/n 30308009
- 13) Spring valve p/n 100110800
- 14) 2s-1m valve 1034005001020
- 15) LV p/n 22690054007

All lines synflex  
or rubber are 1/2"  
to air pots

